

P. Ponk Aviation
Service Bulletin

SB11-01
FAA Approved

November 18, 2011

Title: SUPERSEDED PARTS

Models Affected: P. Ponk O-470-50 Engines modified under
STC SE4985NM
STC SE4988NM

and P. Ponk O-470-50 Engines installed under
STC SA02092SE
STC SA00468WI
STC SA5664NM
STC SA5966NM

Reason: Over a period of time, engine and accessory part numbers used in production and installation of Continental / P. Ponk O-470-50 Engines have become superseded by the manufacturers.

For the Supplemental Type Certificates listed above, this Service Bulletin permits use of manufacturer's replacement parts, accessories and PMA parts that supersede the original part numbers, as provided below. This Service Bulletin is included in the type design (i.e. Master Drawing List) for the STC's listed above, as required by 14CFR21.31.

1. Slick PN: 6210 Magneto has been superseded by a PN: 6310 Magneto.
2. Continental PN: 536421 and 653631 Gears have been superseded by PN: 657175 Gear.
3. Continental PN: 631845, 655430, 655516 and 656030 Gears have been superseded by PN: 656818 Gear.

END OF LISTING -

Note: It is not mandatory to upgrade to later part numbers unless it is mandatory by an FAA Airworthiness Directive (AD).

P. Ponk Aviation
CAMANO ISLAND AIRFIELD
1212 MOORE ROAD #2
CAMANO ISLAND, WA. 98282-8820

PHONE: 360 629-4812
FAX: 360 629-4811
WEB: www.pponk.com
email: info@pponk.com